

Part Number:

Part Description: HEAD LIGHT GUARD X-MAX 300


Installation / Parts List / Bill of Material for Mounting

NO.	Description	Quantity	Torque*(N-M)	Remarks**
1	Socket button head screw M5x25mm	4		Use Liquid Thread Locker
2	Washer M5	10		
3	Washer Rubber 6x15mm	4		
4	Bush Delrin M6 15x8mm	2		
5	Delrin Black M6 15x5mm	2		
6	AD T HLG	1		
7	AD B HLG	1		
8	HLG	1		
9	Socket button head screw M5x10mm	6		Use Liquid Thread Locker


SRC Design uses Metric System of Measurement and all dimensions in Millimeters

Recommended to use the Torque specified in the table

Denotes Usage of Liquid Thread Locker in specified Locations



RIGHT (R)




LEFT (L)


1

Remove the left and right screws,  
, according to the illustration

A R+L



A R+L




2

Prepare the parts and assemble  
according to the illustration.


**A** R+L

**3**

Insert Original screw and part as illustrated.




**B**



**4**

Insert Original screw as illustrated.

**B**







**5**

Insert Original screw and AD B HLG as illustrated.

6

**B C** R+L

Prepare the parts and assemble according to the illustration.



**Make sure they are inserted correctly.**